

Seattle City Light

Jorge Carrasco, Superintendent

September 27, 2006

Mr. Daniel Duncan Regional PCB Program Coordinator US EPA Region10 1200 Sixth Avenue OCE-084 Seattle, WA 98101 SEP 2 8 2006

U.S. EPA REGION 10
OFFICE OF COMPLIANCE AND ENFORCEMENT

Dear Mr. Duncan:

Georgetown Steam Plant Interim Action Report

Attached for your review is the final report for the Interim Action at the Georgetown Steam Plant property. The action involved removing PCB-contaminated soils from the border between the Steam Plant and North Boeing Field. The goal was to stabilize the site and prevent potentially contaminated soil from migrating onto the North Boeing Field facility.

This work was conducted as the first phase of a site characterization effort, which will be ongoing over the next several months. We anticipate having a site characterization plan ready for your review sometime in November.

If you have any questions on the Interim Action report, or the development of our characterization plan, please contact me at your convenience. I can be reached by phone at 206-233-2192 or by e-mail at <a href="wanda.schulze@seattle.gov">wanda.schulze@seattle.gov</a>.

Sincerely,

Wanda B. Schulze

Senior Environmental Analyst Environmental Affairs Division

wbs

Enclosure

USEPA REG